



Certificate of Visual Inspection	
PacRim Job Number	16725
Project Name	DC Multiple Projects
Project Address:	930 Tacoma Ave South
Client:	Pierce County Facilities Management
Work Area / Work Completed:	925 building, east bathrooms / class 2 flooring tile abatement

Following this section is a "Certificate of Visual Inspection". This certification shall be completed by the Contractor and certified by Owner's Consultant. Submit completed Certificate with application for final payment. Final payment will not be made until this certification is executed.

Certificate of Visual Inspection	
In accordance with Section 01577 "Project Decontamination", the Contractor's Certified Supervisor hereby certifies that he has visually inspected the work area (all surfaces, including: pipes, beams, ledges, walls, ceiling and floor, decontamination unit, sheet plastic, etc.) and has found no dust, debris or residue.	
Contractor Printed Name:	Stig Johnson
Contractor Signature:	
Contractor Title:	Abatement Supervisor
Contractor Signature Date:	30-Oct-2019
Contractor E-mail: (Email Copy to)	
Project Representative Certificate	
Owner's Consultant has accompanied the Contractor on his visual inspection and verifies that this inspection has been thorough and, to the best of his knowledge and belief, the Contractor's certification above is true and accurate.	
PacRim Representative Name:	Tyler Sadler
PacRim Project Representative Signature:	
PacRim Representative Title:	Project Manager
PacRim Representative Signature Date:	30-Oct-2019
Inspection Result:	Pass
Email to: (PacRim):	