



Clearance Inspection Checklist	
Job Number	16725
Project Name	DC Multiple Projects
Project Address:	930 Tacoma Ave South
Project area in facility:	930 building, suite 534
Client:	Pierce County Facilities Management
Client Job Number:	
Visual	
Visual Date and Time	21-Oct-2019 08:00
Area Cleaned & Wet Wiped?	Yes
Removal surfaces clean?	Yes
First layer of floor removed?	N/A
Lock down tinted?	N/A
Containment encapsulated?	N/A
Hard to reach/see areas inspected?	Yes
Repeat clean if Necessary	No
Visual Notes/Comments	All TSI within the current scope of work has been fully abated? No dust or material residue left behind.
Technician conducting visual:	Tyler Sadler
Technician signature	
Air Clearance	
Air Clearance -- Date and Time	21-Oct-2019 08:50
Clearance Air Sample Number(s):	1021-03, 1021-04
Clearance Air Sample Result(s) (Fibers/cc):	F/CC=<0.004
Encapsulant applied and dry before air sampling?	N/A
Elapsed time since encapsulation:	N/A
Clearance below specified level?	Pass
Technician reading air clearance:	Tyler Sadler
Email Report to:	

Area Photo:

