



Clearance Inspection Checklist	
<b>Job Number</b>	16725
<b>Project Name</b>	DC Multiple Projects
<b>Project Address:</b>	930 Tacoma Ave South
<b>Project area in facility:</b>	5th Floor, Project north work area
<b>Client:</b>	Pierce County Facilities Management
<b>Client Job Number:</b>	
Visual	
<b>Visual Date and Time</b>	17-Oct-2019 04:12
<b>Area Cleaned &amp; Wet Wiped?</b>	Yes
<b>Removal surfaces clean?</b>	Yes
<b>First layer of floor removed?</b>	N/A
<b>Lock down tinted?</b>	N/A
<b>Containment encapsulated?</b>	N/A
<b>Hard to reach/see areas inspected?</b>	Yes
<b>Repeat clean if Necessary</b>	No
<b>Visual Notes/Comments</b>	Paper wrap with ACM tar mastic has been left on roof drain pipes, until get confirmation that it is included in PNE scope of work.
<b>Technician conducting visual:</b>	Melanie Bryce
<b>Technician signature</b>	
Air Clearance	
<b>Air Clearance -- Date and Time</b>	17-Oct-2019 04:45
<b>Clearance Air Sample Number(s):</b>	1017-01
<b>Clearance Air Sample Result(s) (Fibers/cc):</b>	<0.004 f/cc
<b>Encapsulant applied and dry before air sampling?</b>	N/A
<b>Elapsed time since encapsulation:</b>	
<b>Clearance below specified level?</b>	Pass
<b>Technician reading air clearance:</b>	Melanie Bryce
<b>Email Report to:</b>	

**Area Photo:**

