



Clearance Inspection Checklist	
Job Number	16725
Project Name	DC Multiple Projects
Project Address:	930 Tacoma Ave South
Project area in facility:	6th Floor, east side of construction area. N-S pipe run.
Client:	Pierce County Facilities Management
Client Job Number:	
Visual	
Visual Date and Time	16-Oct-2019 09:15
Area Cleaned & Wet Wiped?	Yes
Removal surfaces clean?	Yes
First layer of floor removed?	Yes
Lock down tinted?	N/A
Containment encapsulated?	N/A
Hard to reach/see areas inspected?	Yes
Repeat clean if Necessary	No
Visual Notes/Comments	Glovebag removal only
Technician conducting visual:	Melanie Bryce
Technician signature	
Air Clearance	
Air Clearance -- Date and Time	16-Oct-2019 09:34
Clearance Air Sample Number(s):	1016-05
Clearance Air Sample Result(s) (Fibers/cc):	<0.004 f/cc
Encapsulant applied and dry before air sampling?	N/A
Elapsed time since encapsulation:	
Clearance below specified level?	Pass
Technician reading air clearance:	Melanie Bryce
Email Report to:	

Area Photo:

